










Connector Type	Cable Type	Connector Components	Tools Required
	S/R .047"	 <p>CONNECTOR HOUSING</p>  <p>FERRULE</p>  <p>BACK BODY</p>	
<p>Procedure</p> <p>1</p>	<p>Assemble connector as shown (see also page 2).</p>		
<p>Procedure</p> <p>2</p>	<p>Slide ferrule over outer conductor, seat firmly and solder.</p>		
<p>Procedure</p> <p>3</p>	<p>Trim outer conductor and dielectric. It should be flush with the ferrule. Point center conductor as shown.</p>		
<p>Procedure</p> <p>4</p>	<p>Before proceeding please make sure that the connector housing assembly is completed properly with the center contact assembly, inner housing and the small dielectric (as shown on page 2). Attention: Do not install the small dielectric reverse!</p>		

Connector Type	Cable Type	Connector Components	Tools Required
	S/R .047"	 <p>CONNECTOR HOUSING</p>  <p>FERRULE</p>  <p>BACK BODY</p>	
<p>Procedure</p> <p>5</p>	<p>Insert cable assembly into connector housing and torque to 30 inch pounds (3.4 Nm).</p>	